MID WHEELS

SQ27

Black Polish That Accentuates the Long-Spoke Design

Black Polish
17x7J+38

Black Polish
15x6J+45

Black Polish
15x5.5J+43

Spec

Product Name	SQ27 Black Polish
Size	12inch / 13inch / 14inch / 15inch / 16inch / 17inch / 18inch
Construction Method	Cast 1pc. Wheel Made in China
Safety Standards	JWL VIA compliant *12x4.00B is JWL-T compliant
Color	Black Polish
Included	Center cap, valve
Optional	Center cap ¥3,000 (ex. tax), valve ¥400 (ex. tax)

Prices are noted in Japanese YEN(JPY). Specifications in the English version are intended for customers outside of Japan and do not include Japan sales tax.

SIZE	INSET ( ): HUB CLEARANCE (mm)	HOLE	P.C.D.	HUB BORE (ϕ)	DRILL (ϕ)	PRICE	CALIPER CLEARANCE	DISK PROTRUSION (mm)	Load (kg)	Load (lbs)
						BKP				
12x4B	42(33)	4	100	67	32-13	22,000	-	12.9	360	794
14x4.5J	45(33)	4	100	67	32-13	25,000	***	9.9	500	1102
14x5.5J	45(35)	4	100	67	32-13	26,000	-	5.5	500	1102
	38(42)									
15x4.5J	45(33)	4	100	67	32-13	28,000	***	9.9	500	1102
15x5.5J	50(35)	4	100	67	32-13	29,000	-	10.1	500	1102
	43(42)									
15x6J	45(42)	5	100	67	32-13	29,500	-	9.9	505	1113
	52(35)		114.3	73					690	1521
16x6.5J	47(43)	5	100	67	32-13	35,000	-	9	530	1168
	38(52)		114.3	73					690	1521
	48(42)									
	53(37)									
17x7J	50(40)	5	100	67	32-13	41,500	-	6.1	540	1190
	55(36)		114.3	73					690	1521
	48(42)									
	38(52)						**			
18x7J	50(36)	5	114.3	73	32-13	48,000	-	3.1	690	1521

18x8J	42(41)	5	114.3	73	32-13	49,000	**	3.5	690	1521

Caution
∗The Mark's inset is the Big Caliper compatible model for 51FUGA, V36 Skyline Coupe, and Z34.
** The marked inset is a model for Crown 3.5L big calipers.
***The mark indicates models compatible with Solio and Delica D:2 calipers.
▲ Mark is specifically designed for Toyota flat seat nuts, with a dedicated hub-centric type. Please take note.
■ Mark is for 14R spherical seat M14×1.5 bolt vehicles only, with a dedicated hub-centric type. Please take note.
16 to 18-inch wheels are compatible with the air sensor valves of LEXUS and the E52 Elgrand.
This product has the disk protruding beyond the rim, so please take care when installing.